



n.	code
----	------




51001701400






n.	code
1	SBC0029609
2	S340052793Z
3	S340006293Z
4	SCC0001969
5	SCC0000578
6	S340023593Z
7	SBC0006038
8	S340017593Z
9	S340000493Z
10	S340021993Z
11	SBA0018033T
12	S340001593Z
13	S3401776ZZZ
14	SBA0017753V
15	SCA0002298
16	S340514093A
17	SBC0028338
18	SBC0026666V
19	SBA0017727V
20	S340078293Z
21	SBA0016355




51001700100



n.	code
1	SBC0029609
2	S340052793Z
3	S340006293Z
4	SCC0001969
5	SCC00000578
6	S340023593Z
7	SBC0006038
8	S340017593Z
9	S340000493Z
10	S340021993Z
11	SBA0018033T
12	S340001593Z
13	S3401776ZZZ
14	SBA0017383V
15	SCA0002299
16	S340514093A
17	SBC0028338
18	SBC0026666V
19	SBA0016961V
20	S340078293Z
21	SBA0016355



51001700200



n.	code
1	SBC0029609
2	S340052793Z
3	S340006293Z
4	SCC0001969
5	SCC0000578
6	S340023593Z
7	SBC0006038
8	S340017593Z
9	S340000493Z
10	S340021993Z
11	SBA0018033T
12	S340001593Z
13	S3401776ZZZ
14	SBA0017961V
15	SCA0002038
16	S340514093A
17	SBC0028338
18	SBC0026666V
19	SBA0017964V
20	S340078293Z
21	SBA0016355



51001700300






n.	code
1	SBA0006535*
2	S330221593A
3	SBA0004851*
4	SBC0010239T
5	S340005393Z

51001701500





n.	code
1	SBA0011178
2	S350051593Z
3	S3210008693A
4	SBC0018979T
5	S3401483ZZZ
6	SCA0002077
7	SCA0001552
8	SBC0026739
9	S340003692Z

51001701600





n.	code
1	S471135200A
2	S321680847A
3	SBA0017986
4	S340190493Z
5	S320891747A
6	S340065093A
7	S340021993Z
8	S340198093Z
9	SCC0002058
10	S340006193Z
11	S4204303ZZZ
12	SCC0000047
13	S320698993A
14	S321680547A
15	S340198093Z
16	S3401776ZZZ
17	S321680547A
18	S3403390ZZZ
19	S331821400A
20	S340297593Z
21	S340006293Z
22	S340174993Z
23	SBC0012058
24	S340016093Z
25	S340017593Z
26	S340028093Z
27	S340012393Z
28	SBC0012017
29	S340514093A
32	S340524800A
33	S340000493Z
34	S340021993Z
35	S340040393Z
36	S4204254ZZZ
37	S370033693A

51001700400





n.	code
1	S470896000A*
2	S331452492C
3	SBC0000633*
4	S3402779ZZZ
5	S3402778ZZZ

51001701700





n.	code
1	S470993500A
2	S310182100A
3	S320750800A
4	S310173800A
5	S331825000A
6	S3403039ZZZ
7	S331824900A
8	S340073593Z
9	S331824792A
10	S340073593Z







n.	code
1	S470993000A
2	SCA0000168
3	S320742147A
4	S340012493Z
5	S331823893A
6	S331822793A
7	S340101693Z
8	S320605693A
9	S3400017ZZZ
10	S340004793Z
11	S340304092Z
12	S3403011ZZZ
13	S3403043ZZZ
14	S331823900A
15	S340077493Z
16	S340000392Z
17	S340011293Z
18	S330491693Z
19	S3401240ZZZ
20	S331824500A
21	S3401577ZZZ
22	S340006892Z
23	S3400017ZZZ
24	S331824600A
25	S331824200A
26	S440639700A
27	SCA0000168

51001701900




n.	code
1	S470993200A
2	S340006193Z
3	S320743500A
4	S370033500A
5	S3400141ZZZ
6	S310173700A*
7	S340002393Z
8	S440639000A
9	S340011293Z

51001702000




n.	code
1	SBA0007313
2	S3210008693A
3	SCA0001030
4	SBC0010739
5	S340220592Z
6	S340012293Z
7	S440857347A
8	S350051593Z
9	S340002193Z
10	S340017593Z
11	S340012493Z
12	SBC0012393T
13	S3401483ZZZ
14	S3400014ZZZ
15	S332981800A
16	S340003692Z
17	SBC0012531T
18	SBA0007579T
19	SBC0012507T
20	SBC0012508T


51001702100




n.	code
1	SBA0018266
2	S340513993A
3	S340223393Z
4	S340006293Z
5	S340022993Z
6	S340004393Z
7	SBC0027438T
8	S3216451LZA
9	S340174993Z
10	S340006293Z
11	S340093493Z
12	S380594400A
13	SCA0000302
14	S3403210ZZZ
15	S380594900A
16	SBC0027543V
17	S332208693A
18	S340001593Z
19	S3403414ZZZ
20	S321635293A
21	SBA0016678
22	S332635000A
23	S380582600A
24	S340514093A
25	S380594800A
26	S340000293Z
27	SCA0000133



51001700500




n.	code
1	SBA0018266
2	S340513993A
3	S340223393Z
4	S340006293Z
5	S340022993Z
6	S340004393Z
7	SBC0027438T
8	S3216451LZA
9	S340174993Z
10	S340006293Z
11	S340093493Z
12	S380594400A
13	SCA0000302
14	S3403210ZZZ
15	S380594900A
16	SBC0027543V
17	S332208693A
18	S340001593Z
19	S3403414ZZZ
20	S321635293A
21	SBA0017784
22	SBC0005099
23	S380582600A
24	S340514093A
25	S380594800A
26	S340000293Z
27	SCA0000133





51001700600







n.	code
1	SBA0008112
2	SCA0000108
3	S340012393Z
4	S340028393Z
5	SBC0000499T
6	SBC0000502
7	SBC0000500V

51001702200





n.	code
1	S471428200A
2	SBC0000501T
3	S310151200A*
4	S332950093A
5	S331907681A
6	S332945592A

51001702300





n.	code
1	SBA0016954
2	S340017593Z
3	S340005193Z
4	SBC0027643V
5	S3801649ZZZ
6	S3805202ZZZ

51001702400



n.	code
1	SBA0014193V
2	S320926498A
3	S332208492A
4	S332208592A
5	S340012393Z
6	S340129293Z
7	S340028393Z
8	S340091093Z
9	S370031898A
10	S310071605Z
11	S332207592A
12	S320926993A
13	S310195800A
14	S340006293Z
15	S340223393Z
16	SBC0027769V
17	S340002693Z
18	SBC0027636
19	S340000193Z
20	S340004393Z
21	S340514093A
22	SBC0008060T
23	S340014293Z
24	SBC0006420
25	S332207492A
26	SBC0028564V
27	SCA0002198
28	SBC0028129
29	S340055893Z
30	S340034193Z
31	S340017593Z
32	S340023593Z



51001700700



n.	code
1	SBC0008523T
2	SBA0005213
3	SBC0008524T
4	S340012393Z
5	S340058493Z
6	SCA0001050
7	SBC0011889T
8	S340010492Z
9	S321205693A
10	SBA0005198
11	SBC0011888
12	SBC0011885
13	SBC0011879T
14	S340038293Z
15	SBC0011887T
16	SBC0011560
17	S340083093Z
18	SBC0011559T
19	SBC0011883
20	SBA0007291
21	S310094100B*
22	S321256098A
23	S320699093A
24	S340090293Z
25	SBC0008060T



51001700710








n.	code
1	SBA0017660
2	S340006193Z
3	S340083992Z
4	SBC0026716V
5	SBC0027637T

51001702500





n.	code
1	SBA0014193V
2	S320926498A
3	S332208492A
4	S332208592A
5	S340012393Z
6	S340129293Z
7	S340028393Z
8	S340091093Z
9	S370031898A
10	S310071605Z
11	S332207592A
12	S320926993A
13	S310195800A
14	S340006293Z
15	S340223393Z
16	SBC0027769V
17	S340002693Z
18	SBC0027636
19	S340000193Z
20	S340004393Z
21	S340514093A
22	S340220292Z
23	S340014293Z
24	S300144499A
25	S332207492A
26	SBC0027542V
27	SCA0002198
28	SBC0028129
29	S340055893Z
30	S340034193Z
31	S340017593Z
32	S340023593Z

51001700800






n.	code
1	S340010492Z
2	S321205693A
3	SBA0005198
4	SBC0008057T
5	SBC0007940
6	S321032098A
7	SBC0007951
8	S340083093Z
9	S320699093A
10	SBC0008060T
11	S340058493Z
12	S340012393Z
13	SBC0008523T
14	SBC0008524T
15	SBA0005213
16	S340006293Z
17	SBA0009201
18	S340028393Z
19	SBC0014327T
20	S340180493Z
21	S340033593Z
22	S3311811ZZZ
23	S340018892Z
24	S350240892Z
25	S350235792Z
26	S370025193Z
27	S450544993Z
29	S42004333ZZZ*
31	S430489ZZZ
32	S4304890ZZZ
34	S340040092Z
35	S320282593Z
36	S4305051ZZZ
37	S3450006ZZZ
38	S4304891ZZZ
39	S310177700A*
40	S331910092A



n.	code
1	SBA0014193V
2	S320926498A
3	S332208492A
4	S332208592A
5	S340012393Z
6	S340129293Z
7	S340028393Z
8	S340091093Z
9	S370031898A
10	S310071605Z
11	S332207592A
12	S320926993A
13	S310195800A
14	S340006293Z
15	S340223393Z
16	SBC0027769V
17	S340002693Z
18	SBC0027636
19	S340000193Z
20	S340004393Z
21	S340514093A
22	SBC0008060T
23	S340014293Z
24	S300144499A
25	S332207492A
26	SBC0027542V
27	SCA0002198
28	SBC0028129
29	S340055893Z
30	S340034193Z
31	S340017593Z
32	S340023593Z



51001700900



n.	code
1	S340010492Z
2	S321205693A
3	SBA0005198
4	SBC0008057T
5	SBC0007940
6	S321032098A
7	SBC0007951
8	S340083093Z
9	S320699093A
10	SBC0008060T
11	S340058493Z
12	S340012393Z
13	SBC0008523T
14	SBC0008524T
15	SBA0005213
16	S340224593Z
17	S340006193Z
18	SBA0001946
19	S332305981A
20	S340023493Z
21	S450544893Z
23	S321006883A*
24	S42004332ZZZ
25	SBA0006068
27	S340019192Z
28	S332306393A
29	S340010492Z
30	S320770393A
31	S4305046ZZZ
32	S310177700A*
33	S340028393Z
34	SBC0009454T
35	SBC0029352T
36	S340017793A



51001700910







n.	code
1	SBA0018104V
2	S320926498A
3	S332208492A
4	S332208592A
5	S340012393Z
6	S340129293Z
7	S340028393Z
8	S340091093Z
9	S370031898A
10	S310071605Z
11	S332207592A
12	S320926993A
13	S310195800A
14	S340006293Z
15	S340223393Z
16	SBC0027636
17	S340514093A
18	SBC0000708
19	S340000193Z
20	S340004393Z
21	S332981393A
22	SBC0008060T
23	S340014293Z
24	S340174993Z
25	S332207492A
26	SBC0029464V
27	SCA0002198
28	SBC0028129
29	S340055893Z
30	S340034193Z
31	S340017593Z
32	S340023593Z
33	SBC0027769V
34	S340002693Z

51001701000





n.	code
1	S340010492Z
2	S321205693A
3	SBA0005198
4	SBC0008057T
5	SBC0007940
6	S321032098A
7	SBC0007951
8	S340083093Z
9	S320699093A
10	SBC0008060T
11	S340028093Z
12	S331802593A
13	S332950700A
15	S4304890ZZZ
16	S340032993Z
17	S340032993Z
18	SBA0009893*
19	S3401051ZZZ
20	S340028393Z
21	S340012393Z
22	SBC0009454T
23	S340024293Z
24	SBA0009892*
25	S332950400A
26	S340058493Z
27	SBC0008523T
28	SBC0008524T
29	SBA0005213
30	S340006293Z
31	SBA0009201
32	SBC0014327T
33	S340180493Z
34	S340005893Z
35	S3311811ZZZ
36	S340018892Z
37	S310227300A
38	S340174993Z
39	S332981200A
40	SBC0000477
41	S3400185ZZZ
42	S332981192A
43	S3400727ZZZ
44	SBC0000478
45	S321680700A

51001701010




n.	code
46	S380827300A
47	S332950800A
48	S321680600A
49	S332950592A

51001701010









n.	code
1	SBA0018103
2	S340006193Z
3	S340294592Z
4	SBC0029465V
5	SBC0029466T

51001702500



n.	code
1	SBA0007393
2	S340217593Z
3	SBA0007389
4	SBA0007372
5	S340006193Z
6	S340031893Z
7	SBC0012096
8	SBC0012101V
9	S340000393Z
10	SBC0012083T
11	SCA0000733
12	S340220492Z
13	S340316593Z
14	S340058493Z
15	SBC0012203T
16	SBC0012085
17	SBA0018055
18	S340000393Z
19	S332208592A
20	S332208492A
21	S320926498A
22	S370031898A
23	S340091093Z
24	S340012393Z
25	S340129293Z
26	SBA0018053V
27	S340039093Z
28	SBC0027636
29	SBC0012099
30	S340220292Z
31	S340014293Z
32	S340004393Z
33	S340042093Z
34	SBC0012110
35	S340223393Z
36	S340006293Z
37	S310195800A*
38	S320926993A
39	S332207592A
40	S332207492A
41	SBC0012103V
42	SBA0018060
43	S340514093A
44	S310071605Z
45	S340514093A
46	SBC0009914






51001701100




n.	code
1	S340010492Z
2	S321205693A
3	SBA0005198
4	SBC0008057T
5	SBC0007940
6	S321032098A
7	SBC0007951
8	S340083093Z
9	S320699093A
10	SBC0008060T
11	S340058493Z
12	S340012393Z
13	S332207292A
14	SBA0006340
15	SBC0030289
16	S340061592Z
18	SBC0010285T
19	S340017593Z
20	S340000293Z
23	SCA0000887
24	SBA0006348*
25	S3400163ZZZ
26	SBA0007389
27	S3402906ZZZ
28	SBA0006342
29	SBA0006347
30	SCA0000889
31	SBC0012084V
32	SBC0012108V
33	S340011293Z
34	SCA0000898
35	SBC0009870T
36	SCA0001080*
37	SCA0000897
38	SBC0010760T
39	S340012393Z
40	SBC0030294
41	S340223393Z
42	SBA0007370
43	SBC0012106T
44	SBC0012156
45	SBA0006349*
46	SBC0009866T
47	SBC0009899T

IDM-51001701110







n.	code
48	S340031893Z
49	S340002693Z
50	S340025693Z
51	S340220492Z
52	SBC0009918T
53	SBC0009867
54	S340220392Z
55	SBC0010284T
56	SBC0009904T
57	S310108548Z
58	SBC0009868T
59	S331710800B
60	SBC0012098
61	SCC0000116
62	S340130592Z
63	S340046893Z
64	SBC0012097
65	S3101260ZZZ



n.	code
1	SBA0007369
2	S340017593Z
3	S340041993Z
4	S340003393Z
5	SBC0012086T
6	SBA0007368V
7	SBC0011534T
8	S340006193Z
9	S340031893Z
10	S340319193Z
11	S340055893Z
12	S340217593Z
13	SBA0007155
14	S340023593Z


51001702700






n.	code
1	SBA0007397
2	S340217593Z
3	SCA0000889
4	SBC0012150T
5	SBC0012153T
6	SBA0007386V
7	SBC0012133T
8	S340174993Z
9	S340023593Z
10	S340017593Z
11	S340057793Z
12	S3801095ZZZ
13	S340344893Z
14	S340013592Z
15	SBC0012132T
16	SBA0007385

51001702800



n.	code
1	SCC0001990 H63 C6 B5 S1 UL/CSA 220/240V
1	SCC0000096 H63 C6 B5 S1 3F 220/240V 50Hz 380/415V 50Hz 440V 60Hz
1	SCC0000097 H63 C6 B5 S1 3F 440V 50Hz
2	SCC0001680 H71 C4 B14 3F UL/CSA 220/415V 50Hz
2	S380621600A H71 C4 B14 3F 220/240V 50Hz 380/415V 50Hz 440V 60Hz
2	S380626400A H71 B4 B14 C105 440V 50Hz
3	SCC0001509 H63 C4 B14 3F UL 220/400V 50Hz
3	S380595900A H63 C4 B14 220/240V 50Hz 380/415V 50Hz
3	S380751100A H63 C4 B14 440V 50Hz

51001701200



n.	code	
1	S340000193Z	
2	S3400004393Z	
3	SCC00000577	STD
3	SCC00000546	OPT
4	S340014293Z	

51001701300